

Under Review Notification

Raised By: Steven Drouin

Product #: RBW6405G00631-3G

Date: 19.02.13

Product Name: T//R DUPLEX BEARING REM

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank							Reserved ECN Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		HOLD SHIPMENT	Red Tag/Quarantine Stock	Advise Customers	Stop Production	Re-Work Stock	IPP Under Review	Product Specifications Under Review ("Bluefiles")		
RBW6405G00631-3G-3	RBW6405G00631-3G-3 Rev. A	N	N	N	Y	N	Y	Y	19-581	Design Change

Description of Issue:
 RBW6405G00631-3G-3 has a incorrect bearing (ID 0.668)
 Tolerance diameter Issues
 Please see Engineering for more informaton

Distribution:	VP Operations	Director of Engineering	Customer Support Manager	Technical Support
	Director of Operations	Chief Engineer	Production Engineers	Product Manager - Solutions Provider
	Director Quality Assurance	Engineering Project Managers	Production Planners	Supply Chain Director
	QC Coordinator	Engineering Clerk	Purchasing Manager	Marketing Eugene